



RECAMBIOS PICAÑOL GAMMA



SPARE PARTS FOR PICAÑOL LOOMS



MATEU EXPORT



NOVA
TEKSILAR



1_A_BE212503_J23L00



2_A1_BA212287_J23L01



3_A2



4_A3_BA212500_J23L04



5_A4_BA205901_J23L03



6_A5_BE210208_J23L05



7_A6_BE212314_J23L07



8_A7_BA205893
J23L06



9_A8_BA200899
J23L02



10_A9
END2_M2



11_A10_071
2X7_M2X7



12_A11_V71
2X5_M2X5



13_A12_V71_2X3_M2X3



14_B_BE206132_J23R00



15_B1_BA205749_J23R01-98



16_B2_BA208123_J23R19-98



17_B3_BE206889_J23R03



18_B4_BA208098_J23R18-98



19_B5_BE206570_J23R03



20_B6_BE209963
J23R04



21_B7_BA203131
J23R07



22_B8_BA205194
J23R05



23_B9_BA205193
J23R08



24_B10_BA204350_J23R09



25_B11_BE203500
J23R06



26_B12_BA203455
J23R10



27_B13_V712
5X10_M2 . 5X10



28_B14_V71
2X6_M2X6



29_B15_V71_
2X3_M2X3



30_B16_V71
_2X4_M2X4



31_B17_V71_
2. 5X6_M2. 5X6



32_B18



33_B19_



34_BE212503_J23L00



35_A1_BA212287_J23L01



36_A2_BA212314_J23L07



37_BA205901_J23L03



38_A4_BA213730_J23L08



39_A5_BA210208_J23L05



40_A6_BA200899_J23L02



41_A7_BA205893_J23L06



42_A8_BA213730_J23L08



43_A9_EDN2



44_A10_VZ1_2X6



45_A11_V71_2X5



46_B_BE210503_J23R00_-99



47_B1_BA210480_J23R01-99



48_B2_BE206570_J23R02



49_B3_BE212276_J23R11-99



50_B4_BE206889_J23R03



51_B5_BE209963_J23R04



52_B6_BA205194_J23R05



53_B7_BE203500_J23R06



54_B8_BA203131_J23R07



55_B9_BA205193_J23R08



56_B10_BA204350_J23R09



57_B11_BA203455_J23R10



58_B12_V71 2. 5X5_J23R12



59_B13_V71 2. 5X5_J23R13



Recambios

PICAÑOL



60_B14_V71 2. 5X5_J23R17



61_B15_V71 2. 5X10.5_J23R16



62_B16_V71 2X3



63_A_BE212080_J41L00



64_A1_BA210737_J41L01



65_A2_BA210822_J41L10



66_A3_BA212979_J41L06



67_A4_BA210784_J41L07



68_A5_BA212980_J41L04



69_A6_BA211650-651_J41L02-03



70_A7_BA214065_J41L05



71_A8_END2.5
_M2.5



72_A9_V21_2. 5X3
_M2.5X3



73_A10_V8D
2X4_M2X4



74_A11_V21_
2X3_M2X3



75_A12_V31D
3X6_M3X6



76_B_BE211337_J41R00



77_B1_BE211327_J41R01



78_B2_BE206570_J41R02



79_B3_BE206889_J41R03



80_B4_BA209066_J41R10



81_B5_BE210222_J41R04



82_B6_BA203131_J41R07



83_B7_BE209132_J41R05



84_B8_BE203500_J23R06



85_B9_BE208513_J41R06



86_B10_BA207296_J41R08



87_B11_V71 2X4
_ M2X4



88_B12_V21 2.5X5
M2.5X5



89_B13_V71 2.5X12
M2.5X12



90_A_J35L00_BE218213



91_A2_J35L05_BA216809



92_A3_J35L06_BA216661



93_A1_J35L01_BE216662



94_a4_J35L07_BA216200



95_A6_L35L09_V71 2. 5X6



97_B_J35R00_BE216734



96_A5_J35L10_VZ 2. 5X4



98_B3_J35R05BA216735



99_B4_J35R11-1_BA216691



100_B_J35R01_BE216733



101_B2_J35R07_BE216823



102_B5_J35R19_V71 3X6



103_B6_J35R13_V71 2. 5X5



104_1_BE302719__BA305301_P1576



105_2_BE302719__BE305301_P1576



106_3_BA303583__BA306799_P1395-4



107_BA306798_BA303618__BA304141_P1395-5



108_5_BA203978__BA211475_P1395-16



Recambios

PICAÑOL



109_6_BA205236_
_BA211476_P1395-16



110_7_BE207667_BE306533_P1395-1



111_8_B163176_BA306529_P1393-1



112_9_BE207668_BA306532_P1395-2



113_10_B163175_BA306528_P1393-2



114_11_B160088_P1395-7



115_12_B162176_P1395-20



116_13_BA200965_B163091_P1395-17



117_14_BA213941_P1395-10



118_15_BA210922_P1395-6



119_16_B162339_P1395-9



120_17_B152531
_P1395-11



121_18_B160250_P1395-13



122_19_B2A217767_
_B160089_P1395-15



123_20_B160009
_P1395-14



124_21_B157575_P1395-12



125_22_B162338_P1395-8



Recambios

PICAÑOL



126_23_BA20108
_P1395-19



127_1_Be214117_P2004-7



128_2_BA207094_P1330



129_3_BE204082_P1325



130_4_BA213676




130_4_BA213676



132_6_BA208876_P1897-9



133_7_BA203508_P1897-7



134_8_BA213246_P1328



135_9_BA202923_P1853

136_10_BA207088
_P1852



137_11_BA203848
_P1254-25



138_12_4X9X4_684



139_13_BA202924_P427



140_14_BA202924_P1087



141_21_BE151980_P427



142_22_BE151994_P1439



Recambios

PICAÑOL



143_15_P427



144_16_P427-5



145_17_P427-4



146_18_P427-1



147_19_P427-3



148_20_P427-6



149_1_P1474



150_2_BE216814_P1474-6



151_3_P1474-5



152_4_BA215510_P1474-3



153_5_BA206190_P1474-4



154_6_BA210783_BA214448_P1885-4



155_7_BA214157_P2019-2



156_8_BA214466_P1198-3



157_9_BA210719_BA20873500_P1198-2



158_10_BA211564_BA208736_P1198-1



159_11_BA215061_P1885-7



160_12_B84854_P1294



161_13_BA214539_P1885-6



162_14_P1712



163_15_P1713



164_16_160x60x12-80_P1577



165_17_145x60x12-83_P1577



166_1_99.2002_BA210582_P1149-3



167_2_99.2002_BA207758_P1149-2



168_3_P1149-1



169_4_P1149-4



170_5_99.2002_BA208799_P1149-5



171_99.2002_V3D_M3X16_P1149-6



172_7_P2121



173_8_P2021



174_9_BA214162_P2059



175_10_P2098



176_11_P1885-5



177_12_BA215978_P1897-1

MATEU EXPORT



Recambios PICAÑOL



178_13_B97363_P1897-2



179_14_B162862_P1897-3



80_15_B153898_P2004-3



181_17_BA215782_P1897-11



182_16_P2010



183_1_BA208328_P1329



184_2_BA209763_P1396



185_3_BA210636_P1329-1



186_4_BA208327_P1329-2



187_5_(1)_P1754



188_6_(2)_P2039



189_7_17X120_P1683-1



190_8_16X150_P1683



191_9



192_10



Recambios

PICAÑOL



193_11_BA214004_P1865

194_12_BE212753_BE207576_P1832



195_13



196_14_BE209261_P2086-1



197_15_BE209263_P2086-2



198_1_259325_P1805



199_2_259317_P1805-3



200_3_259318_P1805-5



201_4_259325_P1805-1



202_5_p1805



203_6_P1805-7



204_7_P1897-12



205_8



Recambios

PICAÑOL



206_9_B154553_P2118-1



207_10_P1946



208_11_P2004-1



209_12_8046



210_13_P2004



211_14_P1946



212_2002_1_P1474-2



213_2_99_BA215636_P1140



214_3_2002_P1474-1



215_4_99_BA214596_P1140



216_5_99_BA210764_P1305



217_6_99_BA210764_P1305-1



218_7_99_P1143



219_8_BA211328_P1335-1



220_9_BA213912_P1335-2



221_10_P2022



222_11_2002_P1890



223_12_BA213911_P1335



224_13_99_BA205726_P1327



225_14_P1891



226_1_0.5-0_B200857_858_P1885



227_2_B82971_P1775



228_3_BA202370_23R15



229_4_BA202003_P919



230_5_BA205444_P2019-1



231_6_BA200641_P1326-1



232_7_BA208429_P1326



233_8_BA214975_P1897-5



234_9_M6X32X68



235_10_M6X32X60



236_11_BA217534_M6X32X20



238_13_2002_BA217526_P1860-1



239_15_2002_BA218520_P1860-2



240_14_2002_BA217524_P1860-1



241_1_



242_2_848



243_3



244_4_P1887-6-7



245_4_P1874



246_6_P1391-10



247_7_P1391-9



248_8_



249_9_P1392-8



250_10_P1854-1-2



Recambios

PICAÑOL



251_11_P1391-6



252_12_P1391-7



253_13_P1391-3



254_14_P1391-3



255_15_P565



256_16_P706



257_17_P1319



258_1_



259_2_



260_3_



261_4_B158402_P1897-8



262_5_BA300953_P1817-2



263_6_BA213137_P1817-1



Recambios


PICAÑOL



264_7_B303886_P3121



265_8_B82531_P1885-3



266_9_Ba202185_BA211835_P1192-1



267_1_B87360_P1885-1



268_2_BA211622_P2018



269_3_BA207142_P3118



270_4_B155544_P2041



271_5_BE92331



272_6_B53503_P2004-2

273_7_P2004-6

274_8_P51846_P2004-5

275_9_P51845

_P2004-4



276_10_BE151404_P1463-1



277_11_BE153218_P1463-3



278_12_BE155568_P1780



279_13_B163229_P1897-4



Recambios PICAÑOL



280_14_BA302935
_P1897-13



281_15_BA302936
_P2031



282_16_BA209448_P1897-6



283_1_BA202909_P1418



284_2_BA302313_P1873-1



285_3_BA302314_P1873-2



287_5_BA213945_P1896-2



286_4_BA215286_P1863



288_6_2000_BA212079_P1896-3



289_7_2000_BA215575_P1896-4



290_8_2000_P1896-5



291_9_2002_BA217572_P2105-2



292_1_468557



293_2_4685441



294_3_24V5W



295_4_24V10W



296_5_M12_BE303968_P1581

297_6_M14_BA209609_P1582



298_7_



299_8_B161126_P1580



300_9_B156686_P1579



301_10_BE208333_P1578




302_11_



303_12_



304_13_



305_14_B163113



306_15_



307_1_BA212534_P1818



308_2_BA212535_P1195



309_3_BA200716_P2129-1



310_4_BA200715_P2129



Recambios

PICAÑOL



311_5_BA215536_P3123



312_7_



313_8_



314_9_



315_10_



316_11_



317_1_P2134



318_2_P4080_BA213121



319_3_P1362-2



320_4_P1326-1

MATEU EXPORT



321_5_P4083



322_6_P4082



323_7_P2161-2_BA303494



324_8_P2143



325_9_P2154_BE215587



329_2_BA200715



330_3_P4074



331_4_P4089



332_5_P4065-3



333_5_P4065-3



334_7_P2031-1_N1300146



335_8_P2010-1



336_9_P2168-1



337_10_P4188



338_11_P2162_
BA215945_215915



339_12_M5X25X40



340_13_P2155-2



341_14_P4084
_B15676



342_15_
P2168-2



343_16_
P2139-1



344_17_
P2139-2



345_18_P4086-1
_BA203720



346_19_P4086-2
_BA203547



347_20_P4081
_BA214742



Recambios

PICAÑOL



348_21_P4026_B165682



349_22_P2121



350_23_P4102



351_24_P4068-2



352_25_P2140



353_1_P2155-1_BE208806



354_2_P4065-1_BE208546



355_3_P4065_BE208545



356_4_P4086_BA204824



357_5_P4072-1_BA210281



358_6_P4072-2_BA210282



359_7_P4193



360_8_P4039_B157667



361_9_P4235



362_10_P4066



363_11_P4236_GRB400760



364_12_P4124_BA300890



365_13_P2041



366_14_P4239
_BA301341



367_15_P4240



368_1_P4241_160X80



369_2_P1577_160X60



370_3_P4220-1_85126-118



371_4_P4220-5_85228-118



372_5_P4220-
3_85224-118



373_6_P4220-4
_85226-118



374_7_P4220-5
_85228-118



375_8_P4220-6
_85124-118



376_9_P4220-7
_475303



377_10_P4220-8_466905



378_11_P4220-9_466911



379_12_P4220-10_466898



380_13_P4220-11_466882



381_14_P4220-13_466933



382_15_P4211-1_475404



383_16_P4211-2_475369



384_17_P4211-3_475246



Recambios

PICAÑOL



385_18_P4211_466876



386_19_P4214_466753



387_20_P4215_466781



388_21_P4189_m8x40x20



389_22_P4190_M6X32



390_23_P4197_M6X32X14



391_1_P4060-00_be204081



392_2_P4060_B54225



393_3_P4060_B54218



394_4_P4060-2_b87293_b87297



395_5_P4060-3_B52152



396_6_P4060-9_B88250



397_7_P4060-4_B88250



398_8_P4060-6



Recambios

PICAÑOL



399_9_P4060-5
_B52153



400_10_P4060-7
_B54220



401_11_P4060-8
_B53684



402_12_P4060-10
_B14009



403_13_P1885-14
_B87360



404_14_P1885-15
_B87360



405_1_OPTIMAX_J68L01_BE234365



406_2_OPTIMAX_J68R01_BE234079



407_3_OPTIMAX_J68L02_BA234363



408_4_OPTIMAX_J68R02_BA233129



409_4_OPTIMAX_J68R03_BA233127



410_1_OPTIMAX_P4232



411_2_OPTIMAX_P4231



MATEU EXPORT S.L.

Avda. Bases de Manresa, 27-29, baixos
08242 Manresa, BARCELONA - SPAIN
Tel. 34 - 93 877 11 99, Fax 34 - 93 877 17 14
E-mail: mateu-export@cambrescat.es
Web: www.novateksilar.com